

should be refitted using screw connection: 5028 14 53-00/6 (710)