



**ELECTROLUX HOME PRODUCTS PTY LTD**  
ABN 51 004 762 341

**Technical Bulletin N° REB270**

**Issue: 1**  
**Date: 7/10**

**WEB SITE ADDRESS: [www.partnship.com.au](http://www.partnship.com.au)**

## **CHANGE FROM TAD 0.5 TO NIPPON 0.55 STAINLESS STEEL DOORS**

**Models Affected: WSE6970SA, WSE7000SA**

### **Description of Change**

A change was made to the thickness of stainless steel used to produce the doors on the above models.

This change took affect from (11/08/2009).

The models affected by this change will have their Model Number marked with an “\*1 ” **Service Variant Number**. See the table below for the part numbers.

<b>Model</b>	<b>Description</b>	<b>Part N°</b>
<b>WSE6970SA *01</b>	Fzr Door	1454415
	F C Door	1453049
<b>WSE7000SA *01</b>	Fzr Door	1454392
	F C Door	1453049