




## Gebrauchsanweisung


51 9520 (D)  
51 9609 (GB)  
52 3514 (NL)  
52 3515 (F)  
52 3526 (F)V03  
52 3527 (I)V03  
51 9610 (D)V03  
52 0232 (RU)

## Aufstellanweisung

51 8126 (D)  
51 8129 (D,F,I)  
51 8011 (NL,F,GB)  
51 7986 (I,P,E)  
51 8030 (S,N,SF,DK)  
51 8160 (GR)  
52 0235 (GUS)

## Programmtabelle

51 9521 (D)  
51 9611 (NL)  
51 9612 (F)  
51 9614 (GB)  
51 9615 (I)  
51 9932 (S)  
51 9783




## Zubehör:


Verlängerung für  
 Arbeitsplatten  
 WZ 10040  
 weiß


Unterbauszubehör  
 WZ 10090/01

Bodenbefestigung  
 WX 9756

Höhenanpassung 91 cm  
 WZ 10100







|   | Askoll  | Siemens |
|---|---------|---------|
| 1 | 14 1120 | 14 1283 |
| 2 | 15 1408 | 15 1611 |
| 3 | 09 5162 | 09 5268 |
| 4 | 15 1409 | 09 5269 |

