

PS: Lidar / main PCB / cliff sensor /  
side detect sensor can't be spare part  
due to calibration requirement.

