



**ELECTROLUX HOME PRODUCTS PTY LTD**  
ABN 51 004 762 341

Technical Publication Nº CE238.doc

Issue: 2  
Date: 3/07

**WEB SITE ADDRESS: [www.partnship.com.au](http://www.partnship.com.au)**

***WESTINGHOUSE***

***ELECTRIC  
SQUARE CERAMIC  
COOKTOP***

**NOTE: THIS ISSUE SUPERSEDES ALL PREVIOUS ISSUES**

***MODEL:***  
**PHL668U\*33**


<b>VARIANT CHANGE SUMMARY</b>
<b>*33</b> Replace EGO Touchlite switch (controller) 330 6450 21 with 330 6450 31

<b>First Built Dates:</b>	
<b>PHL668U*33</b>	<b>3/07</b>


<b>CONTENTS</b>	<b>PAGE Nº</b>
FIRST BUILT DATES	2
CONTENTS	3
COOKTOP ASSEMBLY	4 - 5
CIRCUIT DIAGRAM	6

**NOTE: In Parts Listings**

**N.I. = Not Illustrated**  
**N.P.A. = No Part Available**  
**N.P.N. = Not Used on this Model**



ITEM	PART N°	DESCRIPTION Ex. 4875	QTY
1	<b>0255 003 829</b>	GLASS & FRAME ASSEMBLY PHL668U (NOT AS ILLUSTRATED)	1
2	<b>0038 016 832</b>	PANEL BOTTOM C/TOP (PHL668U)	1
3	<b>389 0700 22</b>	ELEMENT CERAM 165 DIA 1200W (S/L)	2
4	<b>389 0826 02</b>	ELEMENT CERAM D 1700/700W (S/L)	1
4a	<b>389 0701 22</b>	ELEMENT CERAM 200 DIA 1800W (S/L)	1
5	<b>300 4233 00</b>	CLIP RETAINING CERAMIC ELEMENT	8
6	<b>330 6450 31</b>	SWITCH EGO TOUCHLITE (ROHS)	1
7	<b>NZ75566</b>	SEAL TOP EGO TOUCHLITE	1
8	<b>NZ75567</b>	SEAL BOTTOM EGO TOUCHLITE CONTROL	1
9	<b>319 5913 00</b>	GROMMET WIRING TOUCH CONTROL	1
10	<b>330 4606 24</b>	TERMINAL HOUSING INCL BRIDGE ROHS (BOX)	1
	<b>330 4606 02</b>	TERMINAL BLOCK KADO 2/4 M DE (COVER)	1
11	<b>0120 009 323</b>	SPRING CLIP FRAME CERAMIC	4
N.I.	<b>ACC014</b>	SCRAPER CERAMIC COOKTOP	1
N.I.	<b>ACC018</b>	CERASEAL GLASS CT PROTECTOR	X
N.I.	<b>ACC019</b>	CLEANER CERAMIC COOKTOP 250ML	X

**WARNING**

IT IS ILLEGAL FOR PERSONS OTHER THAN LICENSED ELECTRICAL MECHANICS OR PERSONS AUTHORISED BY LEGISLATION TO WORK ON THE FIXED WIRING OF ANY ELECTRICAL INSTALLATION. PENALTIES FOR CONVICTION ARE SEVERE.

**IMPORTANT SAFETY NOTICE**

This diagram has been prepared for use by electrically qualified service technicians. The manufacturer cannot be held responsible for the interpretation of its service publications nor for any injury or damage that may occur in connection with their use.