





Gebrauchsanweisung

51 9520 (D)
 51 9665 (I)
 52 3516 (P)
 52 3517 (E)
 51 9609 (GB)
 52 3514 (NL)
 52 3515 (F)

Programmtabelle

51 9521 (D)
 51 9667 (E)
 51 9615 (I)
 51 9666 (P)
 51 9611 (NL)
 51 9612 (F)
 51 9614 (GB)



Unterbauabdeckung
 20 4245

Aufstellanweisung
 51 7967
 (D)
 51 8011
 (NL,F,GB)
 51 7986
 (I,P,E)
 51 8030
 (S,N,SF,DK)
 51 8160
 (GR)

Zubehör:

Verlängerung für
 Arbeitsplatten
 WZ 10040
 weiß

Unterbauszubehör
 WZ 10090/01

Bodenbefestigung
 WX 9756

Höhenanpassung 91 cm
 WZ 10100

